

work and also a small section of Game Farm Road on approach to Hayden Bridge/Game Farm Rd intersection.

Examination and study of the project area revealed that more extensive repairs were required than anticipated. Expanding the extent of the project and doing all required work at one time is most efficient.

CHECKLIST OF ATTACHMENTS:

- MTIP/STIP Amendment spreadsheet – for all deletion/addition/change actions
- MTIP Project Description Form (Form TIP-2) – for all new projects or significant changes

